


CENERE 8518


















x1




30 min




| | | | |
|--|--|--|---|
| A  X12 | B  X12 | C  (4x25mm)X12 | D  X1 |
| E  X4 | F  X1 | G  X2 | |

| | | |
|---|---|---|
| ①  x1 | ②  x2 | ③  x1 |
| ④  x1 | ⑤  x1 | ⑥  x1 |
| ⑦  x2 | ⑧  x1 | |


1



2




3




CENERE1/2


4




5



6



7



8

